

## CASE STUDY • PORT OF BOSTON, LINCOLSHIRE

**PROJECT:** Dismantle and removal of five cranes, redundant port building & redundant waste. LOCATION: Port of Boston, Lincolnshire **CLIENT:** Port of Boston **CONTRACT DURATION:** 8 weeks



Euro Demolition & Dismantling were awarded a contract to carry out the demolition and removal of redundant cranes situated at the active Port of Boston.

There were two Gottwald Cranes weighing 280mt each and three Heavy Dockside Cranes, situated in key working areas.

Works commenced by way of extraction of all oils and greases into designated IBC containers, prior to any removal activities. Utilising our fully trained and experienced oxy-propane cutting operators and excavator machine drivers, the cranes were carefully and safely dismantled. The materials were then treated, stockpiled and disposed from site through the correct channel in readiness for recycling.

The Euro Demolition & Dismantling operatives communicated with the client on a day to day basis to ensure no disturbance to their daily activities were caused during the works. This included liaising with tenants based at the port to ensure that all needs were met.

During our time at Port of Boston, we were also tasked with the removal of an unused port side building. This comprised of an Asbestos Cement Sheeting roof which our fully trained operatives had to carefully remove, and safely dispose of into a designated asbestos waste skip. Our machine operators then commenced with the mechanical dismantling of the metal structure, utilising shears and grabs, ready for stockpiling and recycling. This area is now a clean, open area, ready for future re-use.

Whilst on site we also assisted the client with the removal of redundant waste, in connection with the Environmental Clean-up of the active port.

All works were completed safely and effectively, to the client's satisfaction.

The client says... 'All tasks were executed in a safe and proper manner with minimum disruption to the Port of Boston. All Health & Safety matters were dealt with in a prompt professional manner by those on-site; Paul Thelwell and his team supported by regular visits from Richard Speake their Operations Director and Donna Everitt HSEQ Manager.

I would without a doubt use Euro Demolition in the future and recommend them to other customers'

## Euro Demolition & Dismantling Ltd. Unit 17, Marchington Industrial Estate, Stubby Lane, Marchington, Staffordshire ST14 8LP Tel: 01283 821028 / Email: info@eurodemolition.co.uk / Web: www.eurodemolition.co.uk

## **Head Office**