

## **CASE STUDY: ROYAL MINT, LLANTRISANT**


**PROJECT:** Factory Strip out

**LOCATION:** Llantrisant, South Wales

**CLIENT:** Royal Mint

**CONTRACT DURATION: 14 Weeks** 





Following successful negotiation Euro Demolition and Dismantling Ltd were awarded the contract to remove redundant assets within the Royal Mint Manufacturing Press Room Facility.

These works included the identification, safe removal and disposal of hazardous materials including that of asbestos, oils and transformers PLB's.

Following this material removal we followed up with dismantling the furnaces, rolling and milling equipment, high level ductwork and fume filtration equipment.

Close coordination was key to successfully completing this project as the remaining press room was to be fully operational throughout the project duration.

Particular attention was made to the removal of ACM within oven complex. Also the removal of the ovens due to being located adjacent to a live gas main.